

OWNER

OPERATOR

Name	Sauget WWTP	Name	Robert D. Roddy
Address		Address #	1 American Bottoms Rd.
City	Sauget	City	Sauget
State	IL Zip 62201	State	IL Zip 62201
Phone #	(618) 337-1710	Phone #	(618) 337-1710

PERSON(S) INTERVIEWED

TITLE

PHONE #

Robert D. Roddy	Plant Manager	(618) 337-1710
John Lotzy	Plant Engineer	(618) 337-1710

INSPECTION PARTICIPANT(S)

AGENCY/TITLE

PHONE #

Jeff Schoenbach	Enviro. Spec. I	(618) 346-5120
Steve Woblitt	"	(618) 346-5120

PREPARED BY

AGENCY/TITLE

PHONE #

<i>[Signature]</i>	Enviro. Spec. I	(618) 346-5120
--------------------	-----------------	----------------

SUMMARY OF APPARENT VIOLATIONS

Area	Class	Section

Area	Class	Section

Area	Class	Section

RECEIVED

- 6 JUL 1990

IEPA/DLPC

Sauget Waste Water Treatment Plant
1631215003

REMARKS

On June 25, 1990, Steve Noblitt and I responded to a complaint, concerning a semi-truck that was hauling lagoon sludge from Sauget Waste Water Treatment Plant to Chain of Rocks Landfill. The driver of the truck neglected to lock the rear trailer gate, therefore spilling the material onto the road.

Upon our arrival at the site, we met with Robert Roddy (Plant Manager of Sauget WWTP) and John Lotzy (Sauget WWTP Engineer). Mr. Roddy explained that the accident occurred at 10:30 a.m., with fourteen (14) yards of sludge being released. At the time of the inspection, sand was being incorporated into the sludge to make the material manageable for clean-up. The released sludge stretched 1/4 of mile down Highway 3 (northbound). The majority of the material had been cleaned-up upon our arrival at the site. Illinois Department of Transportation along with Keely Bros. Excavation, conducted the clean-up activities. After the sludge was taken up, a street sweeper was utilized to take-up the residual sludge. The material was disposed of at Chain of Rocks Landfill as a special waste.

Sauget Waste Water Treatment plant has submitted testing results to I.E.P.A. Permit Section which classified the sludge as a special waste. However, Region 6 sampled the sludge on 6/15/90 and has yet to determine if the material is correctly classified. The analytical data submitted to the Agency is very thorough, and gives no reason to assume the material to be anything but a special waste.

On June 26, Steve Noblitt and I did a follow-up investigation at the site. A complaint was registered with Region 6 by Illinois-American Water Company concerning dust from the clean-up irritating workers in the area. The street sweeper used for the clean-up was emptied along the road where the water company was working. Mr. Roddy and John Lotzy accompanied us to the scene and agreed to clean-up the remaining powder by 12:00 a.m. that day.

In conclusion, with the exception of the powder, the material was sufficiently cleaned-up. During the follow-up inspection Mr. Roddy agreed to excavate the remaining sweeping powder. The American Water Company telephoned later that day to confirm the clean-up was sufficient.

jts:

RECEIVED

- 6 JUL 1990

IEPA/DLPC

006301

D.L.P.C. COMPLAINT INVESTIGATION FORM

C-90-65-5

1631215003 - St. Clair
Sauget / Sauget WWTP ()
 Date Received 6/25/90 By M.G. By Phone In Person By Mail
 Complainant Anonymous Respondent American Bottoms
 Address _____ Address #1 American Bottoms Rd.
Sauget, IL. 62201
 Telephone _____ Telephone (618) 732-1710
 Directions To Source Sauget Waste Water Treatment Plant
 Complaint Details Disposing lagoon sludge
without the proper permit.

INVESTIGATION FINDINGS

Date 6/25/90 Time 12:00 By JS & SN
 Interviewed Robert Roddy & Jim Lotz Weather Sunny & Dry - 85° Photos _____
 Violations Observed Refer to Memo dated 6/25/90

Respondent's Remarks _____

FOLLOW-UP ACTION

Refer To _____

File Opened Yes No

RECEIVED

- 6 JUL 1990

IEPA/DLPC

066302
 LPC 41 8/79

~~CONFIDENTIAL~~ *Dg*